

Building	Category	Order	Sub Category	Element/Location	Condition	Priority	Details	Recommendations	Quantity	Unit	Unit Price	Net Total	With soft costs added	Estimated Cost	ADA	Life Safety					
Ag Building/Bus Barn	SiteCivil	01	Drainage	Bus Barn/West Side	Poor	2	Excavate sediment in and around pipe ends causing them to be plugged. Poor drainage conditions.	Excavate excess sediment material and clean culverts.	1	LS	\$2,500.00	\$2,500	\$3,325	\$3,400	No	No					
Ag Building/Bus Barn	SiteCivil	01	Drainage	Drainage/High School Tennis Court/Maintenance Building	Poor	1		Improve site drainage by removing concrete sidewalk, rerouting roof drains to connect to storm sewer, and installing area inlets to drain site to storm sewer.	1	LS	\$61,000.00	\$61,000	\$81,130	\$81,200							
Ag Building/Bus Barn	SiteCivil	03	VehicleRoutes	Bus Barn	Poor	2	Cracked concrete panels around underground structures.	Remove and replace concrete panels.	1	LS	\$10,000.00	\$10,000	\$13,300	\$13,300	No	No					
Ag Building/Bus Barn	ArchitecturalStructural	07	ExteriorRoof	Roof	Fair	3	The pre-engineered metal building features a corrugated metal roof deck. It appears it has been coated with sprayed foam. The roof was not accessed during the assessment. The wood framed metal building features a corrugated metal roof. The install date is unknown. Gutters are present on the north and south sides. Many downspouts are not connected to gutters. Several are damaged.	Perform regular maintenance.	15,000	SF	\$0.00	\$0	\$0	\$0							
Ag Building/Bus Barn	ArchitecturalStructural	08	ExteriorRoof	Roof/Maintenance Building	Poor	1		Replace damaged downspouts and reconnect to gutters. Consider redirecting water away from the tennis courts.	112	LF	\$10.00	\$1,120	\$1,490	\$1,500							
Ag Building/Bus Barn	ArchitecturalStructural	08	ExteriorWalls	Exterior Walls	Fair	3	The corrugated metal wall panels are free from major damage. The is minor dents and corrosion throughout.	Perform regular maintenance.	1	LS	\$0.00	\$0	\$0	\$0							
Ag Building/Bus Barn	ArchitecturalStructural	08	ExteriorWalls	Exterior Wall/Maintenance Building	Fair	2	There is minor damage throughout to the metal wall panels. Heavier damage was observed at overhead door openings.	Replace damaged metal panels and install bollards.	1	LS	\$4,000.00	\$4,000	\$5,320	\$5,400							
Ag Building/Bus Barn	ArchitecturalStructural	09	ExteriorWindows	Windows	Fair	2	Windows on the northeast side appear to be original to construction. They are single pane glass with metal frames. Other windows have been replaced.	Replace original windows.	48	SF	\$95.00	\$4,560	\$6,065	\$6,100							
Ag Building/Bus Barn	ArchitecturalStructural	09	ExteriorWindows	Windows/Maintenance Building	Fair	2	The operable, sliding-style windows appear to be original and are leaking.	Replace windows.	2	Each	\$500.00	\$1,000	\$1,330	\$1,400							
Ag Building/Bus Barn	ArchitecturalStructural	10	ExteriorDoors	Overhead Doors	Fair	3	There are three electric overhead doors that serve the maintenance bays. The remaining ten doors are manually operated. A few of the doors have had lower panels replaced. No major damage was observed. There are three overhead doors. All appear to be functioning. The south door has faded paint.	Perform regular maintenance.	13	Each	\$0.00	\$0	\$0	\$0							
Ag Building/Bus Barn	ArchitecturalStructural	10	ExteriorDoors	Overhead Doors/Maintenance Building	Fair	2		Perform regular maintenance.	3	Each	\$0.00	\$0	\$0	\$0							
Ag Building/Bus Barn	ArchitecturalStructural	10	ExteriorDoors	Exterior Doors	Fair	2	There are two entrance doors that are showing signs of corrosion.	Replace doors.	2	Each	\$5,000.00	\$10,000	\$13,300	\$13,300							
Ag Building/Bus Barn	ArchitecturalStructural	10	ExteriorDoors	Entrance Doors/Maintenance Building	Fair	2	There are two doors which are metal with metal frames. They are starting to rust.	Replace entrance doors.	2	Each	\$3,500.00	\$7,000	\$9,310	\$9,400							
Ag Building/Bus Barn	ArchitecturalStructural	15	InteriorDoors	Original Doors	Poor	1	some doors are damaged and have non-ADA hardware.	Replace doors and hardware.	10	Each	\$2,500.00	\$25,000	\$33,250	\$33,300							
Ag Building/Bus Barn	ArchitecturalStructural	18	InteriorOther	Drinking Fountain ADA	Poor	1	Drinking fountains (other than latest addition) are single height and not ADA compliant	Reconfigure drinking fountains and install bi-level fountains.	2	Each	\$5,000.00	\$10,000	\$13,300	\$13,300							
Ag Building/Bus Barn	ArchitecturalStructural	18	InteriorOther	Restroom ADA	Poor	1	Restrooms do not have proper ADA clear floor space	Remodel restrooms with new finishes and reconfigure to meet ADA requirements.	100	sf	\$300.00	\$30,000	\$39,900	\$39,900							
Ag Building/Bus Barn	MechanicalPlumbing	19	HeatingCooling	Classroom and Lab	Poor	1	There is not proper ventilation.	Add air Handlers	3,300	SF	\$90.00	\$297,000	\$395,010	\$396,000							
Ag Building/Bus Barn	MechanicalPlumbing	19	HeatingCooling	Bus Barn	Poor	1	There is no exhaust in this space.	Install exhaust fan and louvers	1	LS	\$30,000.00	\$30,000	\$39,900	\$39,900		YES					
Ag Building/Bus Barn	MechanicalPlumbing	19	HeatingCooling	Maintenance Shop	Poor	1	There is no exhaust in this space. No heat. Storage of chemical supplies	Install exhaust fan and makeup air	1	LS	\$65,000.00	\$65,000	\$86,450	\$86,500		YES					
Ag Building/Bus Barn	MechanicalPlumbing	19	HeatingCooling	Maintenance Shop	Poor	1	There is no ventilation in this office space	Provide ventilation	1	LS	\$20,000.00	\$20,000	\$26,600	\$26,600							
Ag Building/Bus Barn	ElectricalTechnology	26	PowerSupply	Main Panel/Bus Barn	Fair	2	Branch panels appear to be original to the building and are rusting.	Replace panels.	1	Each	\$4,000.00	\$4,000	\$5,320	\$5,400							
Ag Building/Bus Barn	ElectricalTechnology	26	PowerSupply	Branch Panels/Bus Barn	Fair	2	Branch panels appear to be original to the building and are rusting.	Replace panels.	2	Each	\$4,000.00	\$8,000	\$10,640	\$10,700							
Ag Building/Bus Barn	ElectricalTechnology	28	InteriorLighting	Lighting/Bus Barn	Fair	3	The majority of the existing lighting is comprised of fluorescent light fixtures with manual switching. Code requirements and energy efficiencies such as LED light fixtures, occupancy sensors, daylight harvesting, and dimming control will improve building performance and save electrical costs.	Upgrade lighting to LED light fixtures, incorporate occupancy sensors, daylight harvesting, and dimming controls.	2,000	SF	\$9.00	\$18,000	\$23,940	\$24,000							
Ag Building/Bus Barn	ElectricalTechnology	29	LifeSafety	Fire Panel/Bus Barn	Good	1	Fire alarm panel was upgraded in 2014. Not voice evacuation capable. Current codes require the fire alarm system to be upgraded to a voice evacuation system. Any building modifications or additions could trigger the system to require immediate upgrade. Current system is not capable of being upgraded to a voice evacuation system.	Upgrade system to include voice evacuation.	2,000	SF	\$3.75	\$7,500	\$9,975	\$10,000							
Ag Building/Bus Barn	ElectricalTechnology	01	Drainage	Parking Lot	Fair	3	Drainage features (curb cuts, inlets, pipe outlets) in need of cleaning and reggrading as necessary.	Clean parking lot drainage features (curb cuts, culverts, inlets)	1	LS	\$3,000.00	\$3,000	\$3,990	\$4,000	No	No					
Central Office	SiteCivil	01	Drainage	Ditch/South Approach	Poor	2	Invert clogged and in need of cleaning/reggrading.	Improve site drainage.	1	LS	\$1,000.00	\$1,000	\$1,330	\$1,400	No	No					
Central Office	SiteCivil	01	Drainage	Parking Lot	Fair	3	Water holding in NW corner. Poor pavement grading around area inlet as well.	Improve site drainage.	1	LS	\$8,000.00	\$8,000	\$10,640	\$10,700	No	No					
Central Office	SiteCivil	03	VehicleRoutes	Parking Lot	Fair	2	Repair misc. broken/cracked concrete panels.	Remove and replace concrete panels.	1	LS	\$25,000.00	\$25,000	\$33,250	\$33,300	No	No					
Central Office	SiteCivil	04	PedestrianRoutes	Railing/Southwest Corner Entrance	Poor	1	No railing for steps.	Install new compliant railing.	1	LS	\$1,500.00	\$1,500	\$1,995	\$2,000	Yes	No					
Central Office	SiteCivil	04	PedestrianRoutes	Parking Lot	Poor	1	Insufficient ADA Parking stalls. 5 spaces needed for 101-150 parking stalls provided. Provide parking signs as well.	Provide additional ADA parking stalls as required.	1	LS	\$30,000.00	\$30,000	\$39,900	\$39,900	Yes	No					
Central Office	SiteCivil	04	PedestrianRoutes	Parking Lot	Poor	1	Route from ADA parking stalls to building access are not compliant.	Replace concrete panels to provide ADA compliant access.	1	LS	\$5,000.00	\$5,000	\$6,650	\$6,700	Yes	No					
Central Office	SiteCivil	06	OtherSiteCivil	Approach/Site Entrance	Fair	2	Cracked and uneven panels at entrance/approach.	Replace cracked/uneven panels at entrance.	1,800	SF	\$12.00	\$21,600	\$28,728	\$28,800	No	No					
Central Office	SiteCivil	06	OtherSiteCivil	Site Turf + Landscaping	Fair	3	general landscape elements in disrepair including edging, mulch depth, turf seeding	Seed areas of poor turf establishment. Repair raised or damaged vinyl planting bed edging. Add rock mulch where needed or where it has migrated. Adjust grading at back of retaining walls to ensure proper drainage	1	LS	\$2,000.00	\$2,000	\$2,660	\$2,700							
Central Office	ArchitecturalStructural	07	ExteriorRoof	Roof	Fair	3	The roof consists of a thermoplastic polyolefin (TPO) membrane. There are two roof sections (upper and lower). The membrane was installed over an existing metal roof in approximately 2016. The average useful life is 20-25 years. There are two roof drain basins that are full of debris.	Ensure roof drain basins are kept clean. Perform regular maintenance.	17,800	SF	\$0.00	\$0	\$0	\$0							
Central Office	ArchitecturalStructural	07	ExteriorRoof	Roof Ladder	Poor	1	The ladder used to access the lower level is loose. It appears to be fastened to the wall with two screws.	Install addition fasteners to secure ladder.	1	LS	\$0.00	\$0	\$0	\$0							
Central Office	ArchitecturalStructural	07	ExteriorRoof	Fall Protection	Poor	1	The roof hatch is located within three feet of the roof edge. The demarcated walking path is next to the roof edge with no fall protection.	Install fall protection where walking path is next to the roof edge.	70	LF	\$100.00	\$7,000	\$9,310	\$9,400							
Central Office	ArchitecturalStructural	07	ExteriorRoof	Roof Hatch	Poor	1	The roof hatch lacks fall protection.	Install fall protection.	1	Each	\$1,500.00	\$1,500	\$1,995	\$2,000							
Central Office	ArchitecturalStructural	07	ExteriorRoof	Skylights	Poor	1	The skylights lack fall protection.	Install fall protection.	2	Each	\$1,500.00	\$3,000	\$3,990	\$4,000							
Central Office	ArchitecturalStructural	08	ExteriorWalls	Exterior Walls	Fair	3	The exterior walls are a combination of metal panels, exposed aggregate wall panels, and brick. Materials are free from damage.	Perform regular maintenance.	1	LS	\$0.00	\$0	\$0	\$0							
Central Office	ArchitecturalStructural	09	ExteriorWindows	Windows/Throughout	Fair	2	The windows are an aluminum clad with wood frames. There have been a few windows that have been updated. There is evidence of moisture intrusion throughout.	Replace the windows.	70	Each	\$750.00	\$52,500	\$69,825	\$69,900							
Central Office	ArchitecturalStructural	10	ExteriorDoors	Exterior Doors	Fair	3	The exterior doors are a combination of metal and aluminum storefront assemblies. They are free from damage.	Perform regular maintenance.	6	Each	\$0.00	\$0	\$0	\$0							
Central Office	ArchitecturalStructural	12	InteriorCeiling	Suspended Ceilings	Poor	2	Ceilings are worn and some areas have water damage.	Replace ceiling tiles and grid.	5,000	sf	\$12.00	\$60,000	\$79,800	\$79,800							
Central Office	ArchitecturalStructural	15	Original Doors	Original Doors	Poor	1	some doors are damaged and have non-ADA hardware.	Replace doors and hardware.	56	Each	\$2,500.00	\$140,000	\$186,200	\$187,000							
Central Office	ArchitecturalStructural	16	InteriorFloors	Original flooring	Poor	2	Original flooring is worn and due for replacement	Replace carpet flooring.	5,000	SF	\$10.00	\$50,000	\$66,500	\$66,500							
Central Office	ArchitecturalStructural	17	Original Casework	Original Casework	Fair	2	Original casework is dated, but appears to be functioning well	Replace outdated and damaged casework.	200	LF	\$400.00	\$80,000	\$106,400	\$107,000							
Central Office	ArchitecturalStructural	18	InteriorOther	Second Floor Accessible Route	Poor	1	There is no accessible route to second floor	Install elevator for accessible route to second floor	900	sf	\$500.00	\$450,000	\$598,500	\$599,000							
Central Office	ArchitecturalStructural	18	InteriorOther	Drinking Fountain ADA	Poor	1	Drinking fountains (other than latest addition) are single height and not ADA compliant	Reconfigure drinking fountains and install bi-level fountains.	900	Each	\$5,000.00	\$4,500,000	\$5,985,000	\$6,000,000							
Central Office	ArchitecturalStructural	18	InteriorOther	Restroom ADA	Poor	1	restrooms do not have proper ADA clear floor space	Remodel restrooms with new finishes and reconfigure to meet ADA requirements.	600	sf	\$300.00	\$180,000	\$239,400	\$240,000							
Central Office	MechanicalPlumbing	19	HeatingCooling	HVAC	Poor	2	(2) Condensing Units replaced in 2022, (3) Condensing Units have been replaced but are past their average useful service life. (2) Condensing Units appear to be original	Replace condensing unit	5	SF	\$7,000.00	\$35,000	\$46,550	\$46,600							
Central Office	MechanicalPlumbing	19	HeatingCooling	HVAC	Poor	2	(2) Furnace replaced in 2022, (3) Furnaces have been replaced but are past their average useful service life. (2) Furnaces appear to be original	Replace furnaces and condensing unit	5	Each	\$8,000.00	\$40,000	\$53,200	\$53,200							
Central Office	MechanicalPlumbing	19	HeatingCooling	HVAC	Fair	2	1 Roof Top Unit is past is average useful service life.	Replace Roof Top Unit	1	Each	\$45,000.00	\$45,000	\$59,850	\$59,900							
Central Office	ElectricalTechnology	26	PowerSupply	Branch Panels	Good	3	The branch panels in the electrical rooms are in good condition. The average useful life of a branch panel is 30 years.	Perform regular maintenance and testing.	10	Each	\$0.00	\$0	\$0	\$0							
Central Office	ElectricalTechnology	26	PowerSupply	Main Panel/Electrical Room	Good	3	The service entrance main panel appears to be in good condition, but has no capacity for future circuits.	Perform regular maintenance and testing.	1	Each	\$0.00	\$0	\$0	\$0							
Central Office	ElectricalTechnology	28	InteriorLighting	Lighting/Interior	Fair	3	The majority of the existing lighting is comprised of fluorescent light fixtures with manual switching. Code requirements and energy efficiencies such as LED light fixtures, occupancy sensors, daylight harvesting, and dimming control will improve building performance and save electrical costs.	Upgrade lighting to LED light fixtures, incorporate occupancy sensors, daylight harvesting, and dimming controls.	5,000	SF	\$9.00	\$0	\$0	\$0							
Central Office	ElectricalTechnology	29	LifeSafety	Fire Alarm Panel/Electrical Room	Good	2	The fire alarm system was upgraded in 2013 and is in good condition. The average useful life of a fire alarm system is 15 years.	Perform regular maintenance and testing.	5,000	SF	\$0.00	\$0	\$0	\$0							
Central Office	ElectricalTechnology	30	OtherElectrical	Receptacles	Poor	1	Code requires GFCI protection for all kitchen countertops, bathrooms, and areas with sinks.	Replace Receptacles with GFCI protected receptacles.	200	SF	\$1.00	\$0	\$0	\$0							
Central Office	ElectricalTechnology	33	DataNetwork	IT Equipment/Server Room	Good	3	The equipment in the server room appears to be in good condition.	Perform regular maintenance.	1	Each	\$0.00	\$0	\$0	\$0							
Clark Elementary	SiteCivil	01	Drainage	Playground/Field	Fair	3	Grading appears to hold water in some areas, and has eroded adjacent to hardscape. however, minimal standing water was on site during inspection after a rain event. Some areas had no vegetation.	Perform regular maintenance. Add soil where necessary and re-seed	1	LS	\$1,000.00	\$1,000	\$1,330	\$1,400	No	No					
Clark Elementary	SiteCivil	02	GroundsTurf	Elementary Retaining Wall	Fair	3	Retaining wall separating at corner and exhibiting failure. Caps in disrepair and shifter	Reconstruct wall where damaged repair and reset caps	1	LS	\$2,000.00	\$2,000	\$2,660	\$2,700	No	NO					
Clark Elementary	SiteCivil	02	Chain-link Fencing	Chain-link Fencing	Fair	3	Perimeter chain link fencing in disrepair. Fabric has dislodged from poles and has holes. Various perimeter poles have move out of plumb.	remove and replace chain link fencing poles and fabric where applicable.	1	LS	\$2,000.00	\$2,000	\$2,660	\$2,700							
Clark Elementary	SiteCivil	03	VehicleRoutes	Ingress/Egress	Poor	3	Ingress/Egress for drop-offs is only provided on street. This requires students or parents to park and walk across the street/streets.	Coordinate with City if any other traffic-related improvements are warranted for this area (one-way streets, traffic signals, etc.)	1	LS	\$0.00	\$0	\$0	\$0	No	No					
Clark Elementary	SiteCivil	04	PedestrianRoutes	Parking Area	Poor	1	Non-compliant ADA building access and other pedestrian routes around school.	Replace concrete sidewalk.	1	LS	\$2,000.00	\$2,000	\$2,660	\$2,700	Yes	No					
Clark Elementary	SiteCivil	04	PedestrianRoutes	Entire Site/ Entrance	Poor	1	6" drop out of door.	Replace concrete sidewalk.	1	LS	\$15,000.00	\$15,000	\$19,950	\$20,000	Yes	No					
Clark Elementary	SiteCivil	04	PedestrianRoutes	Entrance A	Poor	1		Replace concrete sidewalk.	500	SF	\$12.00	\$6,000	\$7,980	\$8,000	Yes	No					
Clark Elementary	SiteCivil	05	AthleticRecreation	Elementary Play Surfacing	Fair	1	Play surfacing includes padded tiles and mulching.	Perform safety testing to ensure surfacing materials are meeting fail ratings. Add mulching material and increase padding as needed.	1	LS	\$2,000.00	\$2,000	\$2,660	\$2,700							
Clark Elementary	SiteCivil	05	AthleticRecreation	Elementary Play Surfacing Edging	Fair	2	Edging around play surfacing has lifted in areas and is exposed around perimeter.	Reset/lower edging or adjust grade surrounding perimeter of playground to allow for edging to be flush with grade.	1	LS	\$0	\$0	\$0	\$0							
Clark Elementary	SiteCivil	06	OtherSiteCivil	Pavement/West Entrance A	Poor	1	Asphalt pavement severely cracked. Pavement separating from building.	Pour concrete adjacent to building and replace asphalt pavement.	1	LS	\$10,000.00	\$10,000	\$13,300	\$13,300	No	No					
Clark Elementary	ArchitecturalStructural	07	ExteriorRoof	Roof Ladder	Poor	1	There are no fixed ladders to provide access to different roof elevations.	Install a ladder between roof sections.	3	Each	\$1,500.00	\$4,500	\$5,985	\$6,000							
Clark Elementary	ArchitecturalStructural	07	ExteriorRoof	Roof Hatch	Poor	1	The roof hatch lacks fall protection.	Install fall protection.	1	Each	\$1,500.00	\$1,500	\$1,995	\$2,000							
Clark Elementary	ArchitecturalStructural	07	ExteriorRoof	Roof/Ballasted Section	Fair	2	The 2002 addition to the north appears to have the original ballasted ethylene propylene diene terpolymer (EPDM) roof. There was evidence of														

